

1974 Bellanca Super Viking

Specifications

Year	1974
Serial	75-32-146
Registration	N4205B
TTAF	2545.10
Ad Type	For Sale
Location	Jonesboro, Louisiana
Type	Available
Summary	1974 BELLANCA SUPER VIKING (PRICE REDUCED)
Airframe Details:	TT 2,545.10
Engine Detail	LYCOMING IO-540 300HP - (925.68 TSMOH 1992) SERIAL # L-11896-48
Avionics	GARMIN 345 BLUE AUDIOPANEL GARMIN GNS 430 WASS GARMIN GTX- 327 4 PLACE INTERCOM GARMIN 255A AVIONICS INOVATIONS AICD II AM/FM/CD PLAYER GARMIN GTX 345 ADS-B IN AND OUT TRANSPONDER TRAFFIC AND WEATHER KING KCS 55A SLAVED HSI CENTURY II B AUTOPILOT JPI EDM 830 ENGINE MONITOR
Exterior	OVERALL WHITE WITH MAROON AND BLUE STRIPS 8- 10
Interior:	TAN LEATHER SEATING 8-10
Maintenance:	HARTZELL PROP OVERHAULED 10/25/23 PITOT SYSTEM DUE 12/1/2025 ELT BATTERY REPLACED DUE DATE 10-25 (ALL AD'S COMPLIED WITH 11-8-2023
Addition Features, Equipment or Comments	(Not Available)

Broker

Name	Vaughn West
Email:	vaughn.w@usaaircraft.com
Designation	Area Aircraft Broker
Address	185 Miles Ave NW Canton, OH 44708, Canton, OH 44708 United States
Telephone:	(330) 445-9583
Mobile:	330-445-9583
Skype:	-

Images

Exterior





INSPECTION & MAINTENANCE RECORD	
TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED
	EDDIE HOEK Hanger 22, 1516 Airport Dr. Shreveport La 71106
	21 Sept 2022/ TACH 2255.0 Inspect engine ICW inspection. Cleaned and gapped all spark plugs mag timing. Compression check c/w. #1 72 #2 72 #4 72 #5 72 #6 72 Drained oil and filter. Reserve Ran engine and no leaks noted at this time. Checked all engine mounts, controls, and exhaust. Cleaned air induction filter.
	I certify that this engine has been inspected ICW annual/100 hr inspection and is in airworthy condition. Eddie Hoek A&P/LA. 430314162
	<i>Eddie Hoek</i>

DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED
		PROPELLER MAINTENANCE LOG Description of Inspections and Repairs ALL DATA must be endorsed with the name, rating and certificate number of either the FAA Repair Station or the mechanic.
08 NOVEMBER 2023	N4205B TACH: 2545.1	Performed Annual Inspection on this aircraft. Opened all inspection panels, lubricated, replaced vacuum system gasket RA-B-5-1, installed, installed new air replaced 4 ea Loctite engine shock mounts PN J-9868-5, Re-sealed and serviced in replaced fuel line from flow divider to firewall with new easy. Pilot system checked G48038V, next due 12/01/2025. ELT battery replaced, next due Oct 2025. C/W Detection. No defects found. C/W AD 76-07-112 Magneto/ignition switch, C/P Phasors. C/W AD 08-05-11 Exhaust System. No defects found. C/W AD 14-20-1
		I certify that this aircraft was inspected in accordance with an annual inspection and is in airworthy condition. Russell B Smith A/P/LA #3112876
		<i>Russell B Smith</i>

INSPECTION & MAINTENANCE RECORD		
DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED
08 NOVEMBER 2023	N4205B TACH: 2545.10 TSMOH: 92	Engine was inspected IAW a 100 hr/annual inspection. Plugs cleaned, gapped. Oil changed and serviced with 10 qts AeroShell W100, new oil filter installed. Oil changed and serviced with 10 qts AeroShell W100, new oil filter installed. Magneto to engine timing verified, compression check #1 60/80, #2 60/80, #4, #6 60/80. Cleaned crankshaft sludge tube (propeller sent off for re-assembly with pin 201485, inspected fuel system components in accordance with letter B-105. No defects found. Inspected exhaust components in accordance with Bellanca service letter B-110, no cracks found. Ground ops good.
		I certify that this aircraft was inspected IAW an 100 hr/annual inspection and is in airworthy condition. Russell B Smith A/P/LA #3112876
		<i>Russell B Smith</i>

INSPECTION & MAINTENANCE RECORD		
DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED
08 NOVEMBER 2023	N4205B TACH: 2545.0 TT 2545.0	Propeller and hub unit received by Rym Propeller CRS WN18590K. Re-installed with ops check good.
		I certify that this propeller was inspected IAW a 100 hr/annual inspection and was determined to be in airworthy condition. Russell B Smith A/P/LA #3112876
		<i>Russell B Smith</i>

Interior



Avionics



